

Report of Analysis

Client:	Scalamandre – Tully JV	Date Collected:	04/10/25 12:30
Project:	NYC DOT Harper Street Yard North	Date Received:	04/14/25
Client Sample ID:	WEST-BAY	SDG No.:	Q1803
Lab Sample ID:	Q1803-01	Matrix:	SOIL
		% Solid:	100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.70	H	1	0	0	pH		04/14/25 16:10	9045D
Ignitability	NO		1	0	0	oC		04/14/25 13:22	1030
Reactive Cyanide	0.014	J	1	0.0083	0.050	mg/Kg	04/15/25 08:45	04/15/25 14:49	9012B
Reactive Sulfide	4.76	J	1	0.20	10.0	mg/Kg	04/15/25 12:30	04/15/25 15:39	9034

Comments: pH result reported at temperature 23.4 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits