

Initial and Continuing Calibration Verification

Client: Scalamandre – Tully JV

SDG No.: Q1803

Project: NYC DOT Harper Street Yard North

RunNo.: LB135420

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: Corrosivity	ICV	pH	7.02	7	100	90–110	04/14/2025
Sample ID: Corrosivity	CCV1	pH	2.01	2.00	101	90–110	04/14/2025
Sample ID: Corrosivity	CCV2	pH	12.02	12.00	100	90–110	04/14/2025

Initial and Continuing Calibration Verification

Client: Scalamandre – Tully JV

SDG No.: Q1803

Project: NYC DOT Harper Street Yard North

RunNo.: LB135440

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.09	0.099	91	85-115	04/15/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	04/15/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.23	0.25	92	90-110	04/15/2025
Sample ID: CCV3 Reactive Cyanide	mg/L	0.23	0.25	92	90-110	04/15/2025
Sample ID: CCV4 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	04/15/2025