

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 04/14/25 09:52 Project: Lawrenceville HQ Date Received: 04/14/25 Client Sample ID: LAW-25-0060 SDG No.: Q1808 Lab Sample ID: Q1808-04 Matrix: SOIL % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.53	Н	1	0	0	pН		04/14/25 16:25	9045D
Ignitability	NO		1	0	0	oC		04/16/25 11:30	1030
Reactive Cyanide	0.017	J	1	0.0084	0.050	mg/Kg	04/15/25 08:45	04/15/25 14:49	9012B
Reactive Sulfide	3.19	J	1	0.20	10.0	mg/Kg	04/15/25 12:30	04/15/25 15:45	9034

Comments: pH result reported at temperature 24.2 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits