



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Hit Summary Sheet
SW-846

SDG No.:	Q1822	Order ID:	Q1822
Client:	ENTACT	Project ID:	540 Degraw St, Brooklyn, NY - E9309

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
Client ID : TW-WTS-06								
Q1822-01	TW-WTS-06	Water	Copper	16.6		2.30	10.0	ug/L
Q1822-01	TW-WTS-06	Water	Lead	2.84	J	1.15	6.00	ug/L
Q1822-01	TW-WTS-06	Water	Nickel	594		1.53	20.0	ug/L
Q1822-01	TW-WTS-06	Water	Zinc	1130		8.33	20.0	ug/L



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	ENTACT	Date Collected:	04/15/25
Project:	540 Degraw St, Brooklyn, NY - E9309	Date Received:	04/16/25
Client Sample ID:	TW-WTS-06	SDG No.:	Q1822
Lab Sample ID:	Q1822-01	Matrix:	Water
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-43-9	Cadmium	0.25	U	1	0.25	3.00	ug/L	04/17/25 10:35	04/21/25 18:02	SW6010	SW3010
7440-50-8	Copper	16.6		1	2.30	10.0	ug/L	04/17/25 10:35	04/21/25 18:02	SW6010	SW3010
7439-92-1	Lead	2.84	J	1	1.15	6.00	ug/L	04/17/25 10:35	04/21/25 18:02	SW6010	SW3010
7439-97-6	Mercury	0.076	U	1	0.076	0.20	ug/L	04/21/25 07:20	04/21/25 12:24	SW7470A	
7440-02-0	Nickel	594		1	1.53	20.0	ug/L	04/17/25 10:35	04/21/25 18:02	SW6010	SW3010
7440-66-6	Zinc	1130		1	8.33	20.0	ug/L	04/17/25 10:35	04/21/25 18:02	SW6010	SW3010

Color Before:	Colorless	Clarity Before:	Cloudy	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	Mercury			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits

LAB CHRONICLE

OrderID:	Q1822	OrderDate:	4/16/2025 1:17:00 PM
Client:	ENTACT	Project:	540 Degraw St, Brooklyn, NY - E9309
Contact:	Jarod Stanfield	Location:	L21,VOA Ref. #3 Water

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1822-01	TW-WTS-06	Water			04/15/25			04/16/25
			Mercury	7470A		04/21/25	04/21/25	
			Metals Group4	6010D		04/17/25	04/21/25	