

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Weston Solutions Date Collected: 04/15/25 08:40 Project: Joint Base McGuire Dix Lakehurst JBMDL - DoD Date Received: 04/17/25 Client Sample ID: SS050P-SD43-041525-00 SDG No.: Q1827 Lab Sample ID: Q1827-01 Matrix: SOIL % Solid: 69.3

Parameter	Conc. Qua.	DF MDL	LOD	LOQ / CRQL	Units(Dry Weight) Prep Date	Date Ana.	Ana Met.
TOC	9370	1 43.4	50.0	250	mg/Kg	04/21/25 12:16	Lloyd Kahn

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits