

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

% Solid:

73.3

Fax: 908 789 8922

Report of Analysis

Client: Weston Solutions Date Collected: 04/15/25 09:20 Project: Joint Base McGuire Dix Lakehurst JBMDL - DoD Date Received: 04/17/25 Client Sample ID: SS050P-SD41-041525-00 SDG No.: Q1827 Lab Sample ID: Q1827-04 Matrix: SOIL

ParameterConc.Qua.DFMDLLODLOQ / CRQLUnits(Dry Weight)Prep DateDate Ana.Ana Met.TOC10900143.450.0250mg/Kg04/21/25 12:57Lloyd Kahn

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits