

 $284 \; Sheffield \; Street, \; Mountainside, \; New \; Jersey \; 07092, \; Phone \; : \; 908 \; 789 \; 8900, \\$

Fax: 908 789 8922

Report of Analysis

Client: Ardmore Chemical Date Collected: 04/17/25 12:30 Project: Date Received: PVSC Monthly 2025 04/17/25 Client Sample ID: EFF-WASTE-WATER SDG No.: Q1833 Lab Sample ID: Q1833-01 Matrix: WATER % Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.0014	J	1	0.0012	0.0050	mg/L	04/21/25 09:40	04/21/25 13:21	SM 4500-CN C-16 plus E-16

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits