

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Vartan Manufacturing Corp. Date Collected: 04/25/25 12:02 Project: NYCDEP Permit No. 25-P3067-1 Date Received: 04/25/25 Client Sample ID: CYANIDE-2 SDG No.: Q1836 Lab Sample ID: Q1836-06 Matrix: WATER

% Solid: 0

Parameter	Conc. Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.0012 U	1 0.0012	0.0050	mg/L	04/28/25 08:00	04/28/25 12:38	SM 4500-CN
							C-16 plus E-16

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits