

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Tully Environmental, Inc Date Collected: 04/22/25 11:00 Project: Transfer Station-SPDES Date Received: 04/23/25 Client Sample ID: 001-WILLETS-PT-BLVD(APR) SDG No.: Q1863 Lab Sample ID: Q1863-03 Matrix: WATER % Solid: 0

| Parameter | Conc. Qua. | DF MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|-----------|------------|--------|------------|-------|-----------|----------------|--------------|
| TSS | 33.7 | 1 1.00 | 4.00 | mg/L | | 04/24/25 10:30 | SM 2540 D-15 |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits