

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 04/24/25 09:32 Project: Camden M&R Date Received: 04/24/25 Client Sample ID: RT1491 SDG No.: Q1874 Q1874-04 Lab Sample ID: Matrix: **SOIL** % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	5.39	Н	1	0	0	pН		04/25/25 16:30	9045D
Ignitability	NO		1	0	0	oC		04/28/25 09:58	1030
Reactive Cyanide	0.0086	J	1	0.0084	0.050	mg/Kg	04/28/25 09:50	04/28/25 14:29	9012B
Reactive Sulfide	4.77	J	1	0.20	10.0	mg/Kg	04/28/25 13:40	04/29/25 11:03	9034

Comments: pH result reported at temperature 20.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits