

LAB CHRONICLE

OrderID:	Q1883	OrderDate:	4/25/2025 10:10:00 AM
Client:	Nobis Group	Project:	Raymark Superfund Site
Contact:	Adam Roy	Location:	L41,L51,VOA Ref. #2 Soil,VOA Ref. #3 Water

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1883-01	OU4-PCS-TC-27-0423 25	SOIL			04/23/25			04/25/25
			PCB	8082A		04/29/25	04/29/25	
Q1883-03	OU4-PCS-TC-28-0423 25	SOIL			04/23/25			04/25/25
			PCB	8082A		04/29/25	04/29/25	
Q1883-05	OU4-PCS-TC-29-0423 25	SOIL			04/23/25			04/25/25
			PCB	8082A		04/29/25	04/29/25	
Q1883-07	OU4-PCS-TC-30-0423 25	SOIL			04/23/25			04/25/25
			PCB	8082A		04/29/25	04/29/25	
Q1883-09	OU4-PCS-TC-31-0423 25	SOIL			04/23/25			04/25/25
			PCB	8082A		04/29/25	04/29/25	
Q1883-11	OU4-PCS-TC-32-0423 25	SOIL			04/23/25			04/25/25
			PCB	8082A		04/29/25	04/29/25	
Q1883-13	OU4-VSL-18-042325	SOIL			04/23/25			04/25/25
			PCB	8082A		04/29/25	04/29/25	
Q1883-15	OU4-VSL-19-042325	SOIL			04/23/25			04/25/25
			PCB	8082A		04/29/25	04/29/25	