

Report of Analysis

Client:	Walsh Construction Company II, LLC	Date Collected:	04/28/25 11:50
Project:	Walsh CO-008 Sampling	Date Received:	04/28/25
Client Sample ID:	CO-008R-WC	SDG No.:	Q1907
Lab Sample ID:	Q1907-02	Matrix:	SOIL
		% Solid:	100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.41	H	1	0	0	pH		04/29/25 09:44	9045D
Ignitability	NO		1	0	0	oC		04/30/25 14:22	1030
Reactive Cyanide	0.0083	U	1	0.0083	0.050	mg/Kg	04/30/25 08:50	04/30/25 11:46	9012B
Reactive Sulfide	1.59	J	1	0.20	10.0	mg/Kg	05/01/25 08:50	05/01/25 11:11	9034

Comments: pH result reported at temperature 20.9 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits