

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1907

Project: Walsh CO-032 Sampling

RunNo.: LB135585

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: Corrosivity	ICV	pH	7.01	7	100	90-110	04/29/2025
Sample ID: Corrosivity	CCV1	pH	2.01	2.00	101	90-110	04/29/2025
Sample ID: Corrosivity	CCV2	pH	12.02	12.00	100	90-110	04/29/2025
Sample ID: Corrosivity	CCV3	pH	2.01	2.00	101	90-110	04/29/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1907

Project: Walsh CO-032 Sampling

RunNo.: LB135596

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Hexavalent Chromium	mg/L	0.491	0.5	98	90-110	04/29/2025
Sample ID: CCV1 Hexavalent Chromium	mg/L	0.499	0.5	100	90-110	04/29/2025
Sample ID: CCV2 Hexavalent Chromium	mg/L	0.491	0.5	98	90-110	04/29/2025
Sample ID: CCV3 Hexavalent Chromium	mg/L	0.494	0.5	99	90-110	04/29/2025
Sample ID: CCV4 Hexavalent Chromium	mg/L	0.494	0.5	99	90-110	04/29/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1907

Project: Walsh CO-032 Sampling

RunNo.: LB135605

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID:	ICV1						
Cyanide		mg/L	0.099	0.099	100	90-110	04/30/2025
Sample ID:	CCV1						
Cyanide		mg/L	0.24	0.25	96	90-110	04/30/2025
Sample ID:	CCV2						
Cyanide		mg/L	0.23	0.25	92	90-110	04/30/2025
Sample ID:	CCV3						
Cyanide		mg/L	0.25	0.25	100	90-110	04/30/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1907

Project: Walsh CO-032 Sampling

RunNo.: LB135608

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.092	0.099	93	85-115	04/30/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	04/30/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.23	0.25	92	90-110	04/30/2025
Sample ID: CCV3 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	04/30/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1907

Project: Walsh CO-032 Sampling

RunNo.: LB135612

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Ammonia as N	mg/L	0.92	1	92	90-110	04/30/2025
Sample ID: CCV1 Ammonia as N	mg/L	0.94	1	94	90-110	04/30/2025
Sample ID: CCV2 Ammonia as N	mg/L	1	1	100	90-110	04/30/2025
Sample ID: CCV3 Ammonia as N	mg/L	0.97	1	97	90-110	04/30/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1907

Project: Walsh CO-032 Sampling

RunNo.: LB135683

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV COD	mg/L	48.972	50	98	95-105	05/06/2025
Sample ID: CCV1 COD	mg/L	51.007	50	102	95-105	05/06/2025
Sample ID: CCV2 COD	mg/L	47.954	50	96	95-105	05/06/2025

Initial and Continuing Calibration Verification

Client: Walsh Construction Company II, LLC

SDG No.: Q1907

Project: Walsh CO-032 Sampling

RunNo.: LB135683

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
---------	-------	--------	------------	---------------	---------------------------	------------------