

Matrix Spike/Matrix Spike Duplicate Summary

SW-846

SDG No.: Q1907

Client: Walsh Construction Company II, LLC

Analytical Method: 8081B

DataFile : PD088358.D

Lab Sample ID:	Parameter	Spike	Sample Result	Result	Units	Rec	Rec Qual	RPD	RPD Qual	Low	Limits High	RPD
Client Sample ID: Q1912-01MS	MH-EMS											
	alpha-BHC	17.98	0	18.3	ug/kg	102				60	144	
	beta-BHC	17.98	0	16.6	ug/kg	92				54	143	
	delta-BHC	17.98	0	18.3	ug/kg	102				29	151	
	gamma-BHC (Lindane)	17.98	0	18.8	ug/kg	105				61	140	
	Heptachlor	17.98	0	17.6	ug/kg	98				63	135	
	Aldrin	17.98	0	18.5	ug/kg	103				49	139	
	Heptachlor epoxide	17.98	0	17.3	ug/kg	96				41	156	
	Endosulfan I	17.98	0	20.5	ug/kg	114				56	142	
	Dieldrin	17.98	1.9	17.9	ug/kg	89				47	161	
	4,4'-DDE	17.98	0	14.4	ug/kg	80				55	136	
	Endrin	17.98	1.4	18.1	ug/kg	93				57	139	
	Endosulfan II	17.98	0	16.0	ug/kg	89				40	163	
	4,4'-DDD	17.98	0	19.2	ug/kg	107				47	163	
	Endosulfan sulfate	17.98	0.2342	17.3	ug/kg	95				62	139	
	4,4'-DDT	17.98	0.7385	15.3	ug/kg	81				51	146	
	Methoxychlor	17.98	0	14.5	ug/kg	81				54	136	
	Endrin ketone	17.98	0	17.0	ug/kg	95				60	129	
	Endrin aldehyde	17.98	0.897	18.3	ug/kg	97				59	132	
	alpha-Chlordane	17.98	0	18.2	ug/kg	101				39	166	
	gamma-Chlordane	17.98	0	18.3	ug/kg	102				44	175	