

Report of Analysis

Client:	AECOM	Date Collected:	04/29/25 07:00
Project:	Meeker Ave Plumes Superfund Site RI FS	Date Received:	04/29/25
Client Sample ID:	WC-12-S-202504	SDG No.:	Q1913
Lab Sample ID:	Q1913-01	Matrix:	SOIL
		% Solid:	80.5

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.22	H	1	0	0	pH		05/02/25 16:30	9045D
Ignitability	NO		1	0	0	oC		05/05/25 09:35	1030
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		05/02/25 16:00	9095B
Reactive Cyanide	0.010	J	1	0.0083	0.049	mg/Kg	05/02/25 13:20	05/02/25 15:23	9012B
Reactive Sulfide	3.16	J	1	0.20	10.0	mg/Kg	05/02/25 13:20	05/02/25 15:36	9034

Comments: pH result reported at temperature 22.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits