

Report of Analysis

Client:	AECOM	Date Collected:	04/29/25
Project:	Meeker Ave Plumes Superfund Site RI FS	Date Received:	04/29/25
Client Sample ID:	WC-13-S-202504	SDG No.:	Q1913
Lab Sample ID:	Q1913-03	Matrix:	TCLP
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	25.6	U	1	25.6	100	ug/L	05/05/25 12:05	05/06/25 17:43	SW6010	SW3050
7440-39-3	Barium	1170	*	1	72.8	500	ug/L	05/05/25 12:05	05/06/25 17:43	SW6010	SW3050
7440-43-9	Cadmium	2.50	U	1	2.50	30.0	ug/L	05/05/25 12:05	05/06/25 17:43	SW6010	SW3050
7440-47-3	Chromium	10.6	U	1	10.6	50.0	ug/L	05/05/25 12:05	05/06/25 17:43	SW6010	SW3050
7439-92-1	Lead	11.5	U	1	11.5	60.0	ug/L	05/05/25 12:05	05/06/25 17:43	SW6010	SW3050
7439-97-6	Mercury	0.76	U*	1	0.76	2.00	ug/L	05/05/25 07:20	05/05/25 13:48	SW7470A	
7782-49-2	Selenium	48.2	U	1	48.2	100	ug/L	05/05/25 12:05	05/06/25 17:43	SW6010	SW3050
7440-22-4	Silver	8.10	U	1	8.10	50.0	ug/L	05/05/25 12:05	05/06/25 17:43	SW6010	SW3050

Color Before:	Brown	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	TCLP METALS			

U = Not Detected
LOQ = Limit of Quantitation
MDL = Method Detection Limit
LOD = Limit of Detection
D = Dilution
Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
B = Analyte Found in Associated Method Blank
* = indicates the duplicate analysis is not within control limits.
E = Indicates the reported value is estimated because of the presence of interference.
OR = Over Range
N = Spiked sample recovery not within control limits