

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client:CDM SmithDate Collected:04/28/25 14:15Project:Con Ed UTEN Mount Vernon, NYDate Received:04/29/25

Client Sample ID: WC-04282025 SDG No.: Q1915

Lab Sample ID: Q1915-01 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.41	Н	1	0	0	pН		04/29/25 18:00	9045D
Ignitability	NO		1	0	0	oC		05/01/25 12:38	1030
Reactive Cyanide	0.050	U	1	0.0084	0.050	mg/Kg	04/30/25 08:50	04/30/25 11:54	9012B
Reactive Sulfide	1.58	J	1	0.20	10.0	mg/Kg	05/01/25 08:50	05/01/25 11:20	9034

Comments: pH result reported at temperature 22.5 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits