

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 04/30/25 10:24 Project: Aubudon Gas District Date Received: 04/30/25 Client Sample ID: AUD-25-0068 SDG No.: Q1925 Lab Sample ID: Q1925-01 Matrix: SOIL % Solid: 99.4

| Parameter | Conc. | Qua. | DF | MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|--------------|-------|------|----|-----|------------|-------|-----------|----------------|----------|
| Ignitability | NO | | 1 | 0 | 0 | oC | | 05/01/25 13:45 | 1030 |
| pН | 9.42 | Н | 1 | 0 | 0 | pН | | 05/01/25 10:00 | 9045D |

Comments: pH result reported at temperature 24.4 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits