

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: ENTACT Date Collected: 04/30/25 12:00

Project: 540 Degraw St, Brooklyn, NY - E9309 Date Received: 05/01/25

Client Sample ID: WC-A1-04-C SDG No.: Q1929

Lab Sample ID: Q1929-16 Matrix: SOIL

% Solid: 81.5

Parameter	Conc. Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
рН	12.5 H	1 0	0	pН		05/12/25 13:38	9045D

Comments: pH result reported at temperature 21.6 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits