

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Saxton Falls Sand and Gravel Co. Inc. Date Collected: 05/01/25 10:50 Project: Date Received: Stan Hope 05/01/25 Client Sample ID: SMALL-PILE-A SDG No.: Q1936 SOIL Lab Sample ID: Q1936-01 Matrix: % Solid: 90.8

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigl	ıt) Prep Date	Date Ana.	Ana Met.
Cyanide	0.25	J	1	0.045	0.27	mg/Kg	05/06/25 11:00	05/07/25 11:09	9012B
Hexavalent Chromium	0.069	U	1	0.069	0.39	mg/Kg	05/02/25 08:50	05/02/25 13:38	7196A
Trivalent Chromium	0.55	U	1	0.55	0.55	mg/Kg		05/07/25 16:30	6010D

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits