

Report of Analysis

Client:	Saxton Falls Sand and Gravel Co. Inc.	Date Collected:	05/01/25 12:36
Project:	Stan Hope	Date Received:	05/01/25
Client Sample ID:	LARGE-PILE-F	SDG No.:	Q1937
Lab Sample ID:	Q1937-11	Matrix:	SOIL
		% Solid:	89.7

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.
Cyanide	0.081	J	1	0.046	0.27	mg/Kg	05/06/25 11:00	05/07/25 11:22	9012B
Hexavalent Chromium	0.068	U	1	0.068	0.39	mg/Kg	05/02/25 08:50	05/02/25 13:49	7196A
Trivalent Chromium	6.96		1	0.56	0.56	mg/Kg		05/09/25 16:53	6010D

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits