

## Report of Analysis

Client:	Saxton Falls Sand and Gravel Co. Inc.	Date Collected:	05/01/25 13:12
Project:	Stan Hope	Date Received:	05/01/25
Client Sample ID:	LOWER-WALL-PILE-C	SDG No.:	Q1938
Lab Sample ID:	Q1938-05	Matrix:	SOIL
		% Solid:	96.8

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.
Cyanide	0.11	J	1	0.042	0.25	mg/Kg	05/06/25 11:00	05/07/25 11:22	9012B
Hexavalent Chromium	0.070	U	1	0.070	0.40	mg/Kg	05/06/25 09:00	05/06/25 12:16	7196A
Trivalent Chromium	8.93		1	0.52	0.52	mg/Kg		05/09/25 17:05	6010D

Comments: \_\_\_\_\_

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits