

LAB CHRONICLE

OrderID:	Q1938	OrderDate:	5/1/2025 2:05:00 PM
Client:	Saxton Falls Sand and Gravel Co. Inc.	Project:	Stan Hope
Contact:	Rich Schindelar	Location:	L41,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1938-01	LOWER-WALL-PILE-A	SOIL			05/01/25			05/01/25
			PCB	8082A		05/05/25	05/05/25	
			Pesticide-TCL	8081B		05/05/25	05/05/25	
			TPH GC	8015D		05/07/25	05/08/25	
Q1938-02	LOWER-WALL-PILE-A	Solid			05/01/25			05/01/25
			EPH_NF	NJEPH		05/05/25	05/05/25	
Q1938-03	LOWER-WALL-PILE-B	SOIL			05/01/25			05/01/25
			PCB	8082A		05/05/25	05/05/25	
			Pesticide-TCL	8081B		05/05/25	05/06/25	
			TPH GC	8015D		05/07/25	05/07/25	
Q1938-04	LOWER-WALL-PILE-B	Solid			05/01/25			05/01/25
			EPH_NF	NJEPH		05/05/25	05/05/25	
Q1938-05	LOWER-WALL-PILE-C	SOIL			05/01/25			05/01/25
			PCB	8082A		05/05/25	05/05/25	
			Pesticide-TCL	8081B		05/05/25	05/05/25	
			TPH GC	8015D		05/07/25	05/07/25	
Q1938-06	LOWER-WALL-PILE-C	Solid			05/01/25			05/01/25
			EPH_NF	NJEPH		05/05/25	05/05/25	
Q1938-07	LOWER-WALL-PILE-D	SOIL			05/01/25			05/01/25
			PCB	8082A		05/05/25	05/05/25	
			Pesticide-TCL	8081B		05/05/25	05/05/25	
			TPH GC	8015D		05/07/25	05/07/25	
Q1938-08	LOWER-WALL-PILE-D	Solid			05/01/25			05/01/25
			EPH_NF	NJEPH		05/05/25	05/05/25	