

### Initial and Continuing Calibration Verification

**Client:** CDM Smith

**SDG No.:** Q1956

**Project:** Bergen Point Fueling System

**RunNo.:** LB135675

| Analyte                   |      | Units | Result | True Value | %<br>Recovery | Acceptance<br>Window (%R) | Analysis<br>Date |
|---------------------------|------|-------|--------|------------|---------------|---------------------------|------------------|
| Sample ID:<br>Corrosivity | ICV  | pH    | 7.01   | 7          | 100           | 90-110                    | 05/05/2025       |
| Sample ID:<br>Corrosivity | CCV1 | pH    | 2.01   | 2.00       | 101           | 90-110                    | 05/05/2025       |
| Sample ID:<br>Corrosivity | CCV2 | pH    | 12.02  | 12.00      | 100           | 90-110                    | 05/05/2025       |

## Initial and Continuing Calibration Verification

**Client:** CDM Smith

**SDG No.:** Q1956

**Project:** Bergen Point Fueling System

**RunNo.:** LB135696

| Analyte                                    | Units | Result | True Value | %<br>Recovery | Acceptance<br>Window (%R) | Analysis<br>Date |
|--------------------------------------------|-------|--------|------------|---------------|---------------------------|------------------|
| Sample ID: <b>ICV1</b><br>Reactive Cyanide | mg/L  | 0.093  | 0.099      | 94            | 85-115                    | 05/07/2025       |
| Sample ID: <b>CCV1</b><br>Reactive Cyanide | mg/L  | 0.25   | 0.25       | 100           | 90-110                    | 05/07/2025       |
| Sample ID: <b>CCV2</b><br>Reactive Cyanide | mg/L  | 0.24   | 0.25       | 96            | 90-110                    | 05/07/2025       |