

## Report of Analysis

Client:	Parkway Generation Operating LLC	Date Collected:	05/05/25 10:46
Project:	Parkway Gen Ops - 4001 S Wood Ave Soil Pile	Date Received:	05/05/25
Client Sample ID:	SOIL-PILE	SDG No.:	Q1959
Lab Sample ID:	Q1959-01	Matrix:	SOIL
		% Solid:	87.7

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Ignitability	NO		1	0	0	oC		05/06/25 15:25	1030

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits