

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: Zimmer Biomet Date Collected: 05/05/25 Project: Waste Water Date Received: 05/06/25 Client Sample ID: RECLAIM-TANK SDG No.: Q1967 Lab Sample ID: Q1967-01 Matrix: Water % Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua. D	F MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-66-6	Zinc	22300	D 5	10.0	100	ug/L	05/08/25 10:10	05/13/25 15:04	EPA 200.7	7

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group3

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits