

LAB CHRONICLE

OrderID:	Q1984	OrderDate:	5/8/2025 10:48:00 AM
Client:	Nobis Group	Project:	Raymark Superfund Site
Contact:	Adam Roy	Location:	L41,VOA Ref. #2 Soil,VOA Ref. #3 Water

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1984-01	OU4-PCS-TC-33-0507 25	SOIL			05/07/25			05/08/25
			PCB	8082A		05/12/25	05/12/25	
Q1984-03	OU4-PCS-TC-34-0507 25	SOIL			05/07/25			05/08/25
			PCB	8082A		05/12/25	05/12/25	
Q1984-05	OU4-PCS-TC-35-0507 25	SOIL			05/07/25			05/08/25
			PCB	8082A		05/12/25	05/12/25	
Q1984-07	OU4-TS-24-050725	SOIL			05/07/25			05/08/25
			PCB	8082A		05/12/25	05/12/25	
Q1984-09	OU4-TS-25-050725	SOIL			05/07/25			05/08/25
			PCB	8082A		05/12/25	05/13/25	
Q1984-11	OU4-TS-26-050725	SOIL			05/07/25			05/08/25
			PCB	8082A		05/12/25	05/12/25	
Q1984-13	OU4-TS-27-050725	SOIL			05/07/25			05/08/25
			PCB	8082A		05/12/25	05/13/25	
Q1984-15	OU4-TS-28-050725	SOIL			05/07/25			05/08/25
			PCB	8082A		05/13/25	05/14/25	