

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Date Collected: 05/07/25 12:00

Project: 540 Degraw St, Brooklyn, NY - E9309 Date Received: 05/09/25

Client Sample ID: WC-A1-05-C SDG No.: Q2001

Lab Sample ID: Q2001-07 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	12.0	Н	1	0	0	pН		05/12/25 13:44	9045D
Ignitability	NO		1	0	0	oC		05/12/25 14:30	1030
Reactive Cyanide	0.0093	J	1	0.0083	0.049	mg/Kg	05/13/25 11:55	05/14/25 10:03	9012B
Reactive Sulfide	4.78	J	1	0.20	10.0	mg/Kg	05/12/25 11:00	05/12/25 15:16	9034

Comments: pH result reported at temperature 21.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits