

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 05/09/25 09:29 Project: Camden M&R Date Received: 05/09/25 Client Sample ID: VNJ-220 SDG No.: Q2004 Lab Sample ID: Q2004-02 Matrix: **SOIL** % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	6.45	Н	1	0	0	pН		05/12/25 08:40	9045D
Ignitability	NO		1	0	0	oC		05/13/25 11:35	1030
Reactive Cyanide	0.050	U	1	0.0083	0.050	mg/Kg	05/13/25 11:55	05/14/25 10:03	9012B
Reactive Sulfide	3.17	J	1	0.20	10.0	mg/Kg	05/12/25 11:00	05/12/25 15:25	9034

Comments: pH result reported at temperature 21.2 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits