

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Parkway Generation Operating LLC Date Collected: 05/12/25 11:14

Project: Linden Generating Station - 402 Date Received: 05/12/25

Client Sample ID: 402 SDG No.: Q2016

Client Sample ID: 402 SDG No.: Q2016

Lab Sample ID: Q2016-01 Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Field pH	7.58		1	0	0	pН		05/12/25 11:18	SM4500-H B
TPH	0.40	J	1	0.29	5.00	mg/L		05/15/25 09:45	1664A

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits