

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: PSEG Date Collected: 05/12/25 10:20

Project: Galloping Hills Sub OP Date Received: 05/12/25

Client Sample ID: MH-I SDG No.: Q2017

Lab Sample ID: Q2017-04 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.12	Н	1	0	0	pН		05/13/25 09:15	9045D
Ignitability	NO		1	0	0	oC		05/13/25 14:45	1030
Reactive Cyanide	0.0089	J	1	0.0084	0.050	mg/Kg	05/13/25 13:50	05/14/25 10:26	9012B
Reactive Sulfide	3.17	J	1	0.20	10.0	mg/Kg	05/15/25 08:50	05/15/25 11:06	9034

Comments: pH result reported at temperature 22.4 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits