

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: Scalamandre – Tully JV Date Collected: 05/12/25 13:00

Project: NYC DOT Harper Street Yard North Date Received: 05/13/25

Client Sample ID: B27-SOIL-SAMPLE SDG No.: Q2027

Lab Sample ID: Q2027-03 Matrix: SOIL

% Solid: 88.8

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	10.9	Н	1	0	0	pН		05/14/25 15:35	9045D
Ignitability	NO		1	0	0	oC		05/13/25 15:38	1030
Reactive Cyanide	0.0083	U	1	0.0083	0.050	mg/Kg	05/13/25 13:50	05/14/25 10:32	9012B
Reactive Sulfide	6.37	J	1	0.20	10.0	mg/Kg	05/15/25 08:50	05/15/25 11:20	9034

Comments: pH result reported at temperature 22.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits