

Report of Analysis

TSS	2.00 J	1 1.00	4.00	mg/L		05/16/25 11:25	SM 2540 D-15
TDS	584	1 1.00	10.0	mg/L		05/14/25 12:30	SM 2540 C-15
Parameter	Conc. Qua	n. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
				9	% Solid:	0	
Lab Sample ID:	Q2030-0	1		Ν	Aatrix:	WATER	
Client Sample ID:	402-PSD			S	DG No.:	Q2030	
Project:	Parkway Gen Ops - 4001 S Wood Ave Soil Pile				Date Received:	05/13/25	
Client:	Parkway Generation Operating LLC				Date Collected:	05/13/25 1	2:30

Comments:

- U = Not Detected
- LOQ = Limit of Quantitation
- MDL = Method Detection Limit
- LOD = Limit of Detection
- D = Dilution
- Q = indicates LCS control criteria did not meet requirements
- H = Sample Analysis Out Of Hold Time

- J = Estimated Value
- B = Analyte Found in Associated Method Blank
- * = indicates the duplicate analysis is not within control limits.
- E = Indicates the reported value is estimated because of the presence of interference.
- OR = Over Range
- N =Spiked sample recovery not within control limits