

Lab Sample ID:

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Matrix:

WATER

Fax: 908 789 8922

Q2031-01

Report of Analysis

Client: Parkway Generation Operating LLC Date Collected: 05/13/25 09:40

Project: Linden Generating Station - LRSA Date Received: 05/13/25

Client Sample ID: DSN002 SDG No.: Q2031

% Solid: 0

Parameter	Conc. Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
BOD5	33.4	1	0.20	2.00	mg/L		05/14/25 14:30	SM 5210 B-16
COD	61.2	1	1.50	10.0	mg/L		05/14/25 13:52	SM 5220 D-11
TSS	14.5	1	1.00	4.00	mg/L		05/16/25 11:25	SM 2540 D-15

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits