

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: Q2031

Project: Linden Generating Station - LRSA

RunNo.: LB135771

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: COD	ICV	mg/L	48.972	50	98	95-105	05/06/2025
Sample ID: COD	CCV1	mg/L	51.007	50	102	95-105	05/14/2025
Sample ID: COD	CCV2	mg/L	47.954	50	96	95-105	05/14/2025

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: Q2031

Project: Linden Generating Station - LRSA

RunNo.: LB135839

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID:	ICV						
Field pH		pH	7.02	7	100	90-110	05/13/2025
Sample ID:	CCV1						
Field pH		pH	7.02	7	100	90-110	05/13/2025
Sample ID:	CCV2						
Field pH		pH	7.01	7	100	90-110	05/13/2025

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: Q2031

Project: Linden Generating Station - LRSA

RunNo.: LB135839

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
---------	-------	--------	------------	---------------	---------------------------	------------------