

LAB CHRONICLE

OrderID:	Q2032	OrderDate:	5/13/2025 4:01:00 PM
Client:	CDM Smith	Project:	South River WM Replacement
Contact:	Marcie Ann Encinas	Location:	L41,VOA Ref. #2 Soil,VOA Ref. #3 Water

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2032-01	TP-11	SOIL	VOC-TCLVOA-10	8260D	05/13/25		05/20/25	05/13/25
Q2032-01ME	TP-11ME	SOIL	VOC-TCLVOA-10	8260D	05/13/25		05/21/25	05/13/25
Q2032-02	TP-29	SOIL	VOC-TCLVOA-10	8260D	05/13/25		05/20/25	05/13/25
Q2032-03	TP-29-99	SOIL	VOC-TCLVOA-10	8260D	05/13/25		05/16/25	05/13/25
Q2032-04	TP-24	SOIL	VOC-TCLVOA-10	8260D	05/13/25		05/16/25	05/13/25
Q2032-07	TP-37	SOIL	VOC-TCLVOA-10	8260D	05/13/25		05/16/25	05/13/25
Q2032-08	TP-32	SOIL	VOC-TCLVOA-10	8260D	05/13/25		05/16/25	05/13/25
Q2032-09	COMP-1	TCLP	TCLP VOA	8260D	05/13/25		05/15/25	05/13/25
Q2032-11	FB-05132025	Water	VOC-TCLVOA-10	8260-Low	05/13/25		05/15/25	05/13/25
Q2032-12	TB	Water	VOC-TCLVOA-10	8260-Low	05/13/25		05/15/25	05/13/25