

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 05/16/25 12:20 Project: PSEG Bergen Point Date Received: 05/16/25 Client Sample ID: L2-WC-6 SDG No.: Q2071 Lab Sample ID: Q2071-20 Matrix: SOIL % Solid:

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.73	Н	1	0	0	pН		05/16/25 17:10	9045D
Ignitability	NO		1	0	0	oC		05/19/25 14:15	1030
Reactive Cyanide	0.010	J	1	0.0083	0.050	mg/Kg	05/20/25 10:45	05/20/25 14:11	9012B
Reactive Sulfide	3.17	J	1	0.20	10.0	mg/Kg	05/20/25 08:50	05/20/25 11:15	9034

Comments: pH result reported at temperature 23.2 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

100

OR = Over Range

N =Spiked sample recovery not within control limits