

## Report of Analysis

Client:	First Environment, Inc.	Date Collected:	05/16/25
Project:	Somerset Hills Memorial Park	Date Received:	05/16/25
Client Sample ID:	FB	SDG No.:	Q2072
Lab Sample ID:	Q2072-05	Matrix:	Water
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7439-89-6	Iron	13.5	J	1	11.7	50.0	ug/L	05/20/25 10:05	05/28/25 20:55	6010D	SW3010
7440-23-5	Sodium	434	U	1	434	1000	ug/L	05/20/25 10:05	05/28/25 20:55	6010D	SW3010

Color Before:	Colorless	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	Metals Group3			

U = Not Detected  
 LOQ = Limit of Quantitation  
 MDL = Method Detection Limit  
 LOD = Limit of Detection  
 D = Dilution  
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value  
 B = Analyte Found in Associated Method Blank  
 \* = indicates the duplicate analysis is not within control limits.  
 E = Indicates the reported value is estimated because of the presence of interference.  
 OR = Over Range  
 N =Spiked sample recovery not within control limits