

Report of Analysis

Client:ENTACTProject:540 Degraw St, Brooklyn, NY - E9309Client Sample ID:WC-A1-07A-C						Date Collected: Date Received: SDG No.:		05/13/25 12:00		
								05/19/25		
								Q2078		
Lab Sample ID:	Q2078-15					Matrix:		SOIL		
						(% Solid:	100		
Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	
Corrosivity	12.2	Н	1	0	0	pН		05/20/25 16:55	9045D	
Ignitability	NO		1	0	0	oC		05/20/25 11:00	1030	
Reactive Cyanide	0.010	J	1	0.0083	0.049	mg/Kg	05/20/25 10:45	05/20/25 14:11	9012B	
Reactive Sulfide	1.58	J	1	0.20	10.0	mg/Kg	05/20/25 08:50	05/20/25 11:28	9034	

Comments: pH result reported at temperature 20.8 °C

- U = Not Detected
- LOQ = Limit of Quantitation
- MDL = Method Detection Limit
- LOD = Limit of Detection
- D = Dilution
- Q = indicates LCS control criteria did not meet requirements
- H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

- E = Indicates the reported value is estimated because of the presence of interference.
- OR = Over Range
- N =Spiked sample recovery not within control limits

^{* =} indicates the duplicate analysis is not within control limits.