

В

C

SAMPLE DATA



Client Sample ID:

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

DRAIN-WATER-TANK-1

Report of Analysis

Client: Major Products Date Collected: 05/20/25 11:30

Project: Floor Drain Water 2025 Date Received: 05/20/25

Lab Sample ID: Q2089-01 Matrix: WATER

> % Solid: 0

Q2089

SDG No.:

Parameter	Conc. Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
BOD5	6210	1	0.20	2.00	mg/L		05/22/25 08:50	SM 5210 B-16
TSS	377	1	1.00	4.00	mg/L		05/21/25 10:30	SM 2540 D-15

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits







LAB CHRONICLE

OrderID: Q2089

Client: Major Products

Contact: Paul Bustamante

OrderDate: 5/20/2025 12:19:00 PM

Project: Floor Drain Water 2025

Location: L31

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2089-01	DRAIN-WATER-TANK-	WATER			05/20/25			05/20/25
	1				11:30			
			BOD5	SM5210 B			05/22/25	
							08:50	
			TSS	SM2540 D			05/21/25	
							10:30	