

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Willets Point Asphalt Corporation Date Collected: 05/16/25 10:00

Project: SPDES 2025 Date Received: 05/20/25

Client Sample ID: 002A(JAN-JUNE) SDG No.: Q2091

Lab Sample ID: Q2091-02 Matrix: WATER

% Solid: 0

Parameter	Conc. Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TSS	84.5	1 1.00	4.00	mg/L		05/21/25 10:30	SM 2540 D-15

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits