

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 05/20/25 10:46 Project: Bergen Point Substation Date Received: 05/20/25 Client Sample ID: WATER-K SDG No.: Q2093 Lab Sample ID: Q2093-13 Matrix: WATER % Solid: 0

Parameter	Conc. Qua. DF MDL	LOQ / CRQL Units	Prep Date Date Ana. Ana Met.
pН	7.26 H 1 0	0 pH	05/21/25 10:00 9040C

Comments: pH result reported at temperature 23.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits