

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 05/27/25 12:15 Project: PSEG Durham Ave Test Pits Date Received: 05/27/25 Client Sample ID: TP-3 SDG No.: Q2130 Lab Sample ID: Q2130-02 Matrix: **SOIL**

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.50	Н	1	0	0	pН		05/27/25 15:10	9045D
Ignitability	NO		1	0	0	oC		05/28/25 15:15	1030
Reactive Cyanide	0.015	J	1	0.0084	0.050	mg/Kg	05/28/25 09:10	05/28/25 15:13	9012B
Reactive Sulfide	1.58	J	1	0.20	10.0	mg/Kg	05/28/25 09:10	05/28/25 13:42	9034

Comments: pH result reported at temperature 22.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits