

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 05/27/25 09:08 Project: Camden Gas Plant Date Received: 05/27/25 Client Sample ID: CAM-40626 SDG No.: Q2131 Lab Sample ID: Q2131-05 Matrix: SOIL % Solid: 100

Parameter	Conc. Qu	a. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Flash Point	161	1 0	0	o F		06/02/25 15:15	1010B

Other method reference for flash point: Pensky-Martens Closed Cup Flash Point ASTM D 93 - IP 34

U = Not Detected

Comments:

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits