

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

G Environmental Client: Date Collected: 05/27/25 Project: Banker Date Received: 05/28/25 Client Sample ID: **SUPPLY** SDG No.: Q2133 Lab Sample ID: Q2133-03 Matrix: Water % Solid: Level (low/med): 0 low

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-23-5	Sodium	57500	*	1	434	1000	ug/L	05/29/25 10:15	06/03/25 15:47	6010D	SW3010

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Artifacts:

Comments: Metals Group4

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits