

LAB CHRONICLE

OrderID:	Q2150	OrderDate:	5/28/2025 3:53:00 PM
Client:	CDM Smith	Project:	South River WM Replacement
Contact:	Marcie Ann Encinas	Location:	L41,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2150-01	TP-44	SOIL	PCB	8082A	05/27/25	05/30/25	05/30/25	05/28/25
Q2150-02	TP-42	SOIL	PCB	8082A	05/27/25	05/30/25	05/30/25	05/28/25
Q2150-03	TP-39	SOIL	PCB	8082A	05/27/25	05/30/25	05/30/25	05/28/25
Q2150-04	TP-48	SOIL	PCB	8082A	05/27/25	05/30/25	05/30/25	05/28/25
Q2150-05	TP-47	SOIL	PCB	8082A	05/27/25	05/30/25	05/30/25	05/28/25
Q2150-06	TP-50	SOIL	PCB	8082A	05/27/25	05/30/25	05/30/25	05/28/25
Q2150-07	TP-51	SOIL	PCB	8082A	05/27/25	05/30/25	05/30/25	05/28/25
Q2150-08	TP-52	SOIL	PCB	8082A	05/28/25	05/30/25	05/30/25	05/28/25
Q2150-09	TP-54	SOIL	PCB	8082A	05/28/25	05/30/25	05/30/25	05/28/25
Q2150-10	TP-53	SOIL	PCB	8082A	05/28/25	05/30/25	05/30/25	05/28/25