

## Report of Analysis

Client:	Portal Partners Tri-Venture	Date Collected:	05/31/25 09:30
Project:	Amtrak Sawtooth Bridges 2025	Date Received:	06/02/25
Client Sample ID:	B-187-SB01	SDG No.:	Q2177
Lab Sample ID:	Q2177-03	Matrix:	SOIL
		% Solid:	100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.13	H	1	0	0	pH		06/02/25 16:30	9045D
Ignitability	NO		1	0	0	oC		06/02/25 10:16	1030
Reactive Cyanide	0.0083	U	1	0.0083	0.050	mg/Kg	06/02/25 12:25	06/02/25 15:33	9012B
Reactive Sulfide	3.15	J	1	0.20	10.0	mg/Kg	06/02/25 10:30	06/02/25 14:13	9034

Comments: pH result reported at temperature 20.9 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits