

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Holland Manufacturing Co. Date Collected: 06/03/25 10:30 Project: Pre Treatment Plant 2025 Date Received: 06/03/25 Client Sample ID: **AERATION-1DL** SDG No.: Q2191 Lab Sample ID: Q2191-04DL Matrix: WATER % Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Ammonia as N	389	D	10	15.0	50.0	mg/L	06/05/25 13:50	06/06/25 12:25	SM 4500-NH3
									B plus G-11

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits