

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Tully Environmental, Inc Date Collected: 06/03/25 13:30 Project: Transfer Station-SPDES Date Received: 06/04/25 Client Sample ID: 002-35TH-AVE(JUNE)DL SDG No.: Q2203 Lab Sample ID: Q2203-04DL Matrix: WATER % Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Ammonia as N	5.00	D	5	0.15	0.50	mg/L	06/05/25 13:50	06/06/25 12:25	SM 4500-NH3
									B plus G-11

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits