

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

## **Report of Analysis**

Client: PARSONS Engineering of New York, Inc. Date Collected: 06/04/25 09:15

Project: Con Ed Non MGP – Atlantic Ave 453957.600024.05 Date Received: 06/04/25

Client Sample ID: MW-15-20250604 SDG No.: Q2231

Lab Sample ID: Q2231-03 Matrix: WATER

% Solid: 0

Parameter	Conc. Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Sulfate	32.0	1	0.46	3.00	mg/L		06/05/25 12:00	300.0
TDS	494	1	1.00	10.0	mg/L		06/06/25 12:30	SM 2540 C-15

## Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits